

Additional Nysus Solutions Systems

- Manufacturing Execution
 Systems
- Production Reporting
- Downtime Tracking
- Corrective Action Request Database (CARD)
- Project Management
- Change Management
- Warehouse Management
- Employee Management
- Preventative Maintenance
- On the Job Training (OJT)
- Wire Harness Testing
- Pick to Light Systems

Advantages of working with us

- Web based systems accessible from any web enabled PC
- Constant focus on improving systems while maintaining cost savings for our customers
- Ongoing, 24 / 7 support for the life of the system*

*upon payment of yearly maintenance fee

NYSUS SOLUTIONS. LLC sales@nysus.com (877) 830–8624 www.nysus.com

Nysus Solutions Defect Collection System



When a defect is created, it is critical to document the occurrence so true root cause analysis can be identified. The Nysus Solutions Defect Collection System can be a critical tool in determining where the issues originate and trends that could be affecting your manufacturing processes.

System benefits include:

- → Highlight defect patterns including location
- ➔ Provides time stamping of all defect occurrences
- ➔ Tracks defect by type or reason code
- → Key tool in root cause analysis of defects
- → Integrate to Nysus Solutions MES to allow for FTY reporting
- → Integrate data with MRP system for scrap transactions via batch flat-file integration or XML web services

Standard reporting features:

- → Scatter plot of defect locations by type, part, date, defect, etc.
- ➔ First Time (FTC) Yield Reports
- ➔ Defect occurrences by line, product type, defect group, defect type, associate or time.

		Defect Report Details							
	Defect Reporting	Conversional Inc. Deat				Drilling on Part = GMX320 Front Fascia			
	Select parameters:	Grouping by: Part			Part ID: 1015: GMX320 Front Fascia (12 defects, 0 unzoned)				
	Start Date:	Part	Number of Defects	View Detail	Plot				
Defect Collection	ind bate.	Composite Front Bumper	25	View	Plot				
System	Part Filter:	GMX320 Front Fascia	12	View	Plot		• • •	• 1	
Select Site:	ALL ^ Composite Front Bumper	GMX564 Instrument Panel	2	View	Plot	E.		P	
Enter Defects	GMX320 Front Fascia GMX564 Instrument Panel *	TOTAL	39						
	Gate Filter:						n fa balant		
₩ View Reports	ALL	Ope	en in Excel Print			Expand Image			
view keports	Reason Code Filter:								
Site Admin Only	Assembly: Mis-alignment E Assembly: Missing Push Pin								
🗇 Setup Defect	Assembly: Missing Screw Molding: Contamination								
Collection Data	Group By:								
2.54 R.I.	Part 💌								
	Second-level Grouping:								
	Only show top 10?								
	Add chart goal indicator at:								
	Show As: Grid Chart								
	Run Report								
L									

For additional information on this system and the many other products we can offer your company, contact us today!

Manufacturing GREAT Solutions!